

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

AN205
SSW
1/4-1/2
0.332 mi.
1755 ft.

MANHOLE 40789
STILLWELL AVE - SURF AVE
BROOKLYN, NY

NY Spills S103576326
N/A

Site 3 of 6 in cluster AN

Relative:
Higher

Actual:
6 ft.

SPILLS:

Name: MANHOLE 40789
Address: STILLWELL AVE - SURF AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9812570 / 2002-10-17
Facility ID: 9812570
Facility Type: ER
DER Facility ID: 129847
Site ID: 152987
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 1999-01-12
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1999-01-12
CID: 196
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-01-12
Spill Record Last Update: 2002-10-17
Spiller Name: LISA PARMEGGIA
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 001
Contact Name: LISA PRIMEGGIA
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT e2mis no. 122-382: A.SEEDORF #44746 OS UG REPORTS IN MH40789 W/S STILLWELL AVE 20' N/O SURF AVE HE FOUND 1/2 PINT UNKNOWN OIL ON 100 GALLONS OF WATER. NO OIL FILLED EQUIPMENT IS IN HOLE. HE DOSE NOT SEE A SUMP IN HOLE AT THIS TIME DUE TO THE AMOUNT OF WATER IN STRUCTURE. HOLE IS CONTAINED AND AS FAR AS HE KNOWNS NO SEWERS OR WATERWAYS AFFECTED. HE FOUND THIS UNKNOWN FLUID WHILE DOING ROUTINE WORK. SAMPLE TAKEN (4-6 HRS PRIORITY FOR SAMPLE RESULTS) CLEANUP TO BE DONE WHEN RESULTS COME BACK. E.S.TAG #16134 WAS PLACED. 1/12/99
17:15 HRS -- LAB SEQ# 99-00322, <1.0 PPM PCB. UPDATE: 1/15/99 - 1745 D. BANKHEAD - 64999 - ENV. OPS., REPORTS <1.0 PPM CLEANUP COMPLETE WITH SLIX AND TAG #16134 REMOVED. INCIDENT IS CLOSED."
Remarks: "1/2 PT. OF UNKNOWN OIL IN THE MANHOLE. CON INC NUMBER 122382 ON OIL CONTAINING EQUIPMENT IN MANHOLE, SAMPLE TAKEN CLEAN UP PENDING LAB RESULTS."

All Materials:

Site ID: 152987
Operable Unit ID: 1073098
Operable Unit: 01

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material ID: 312846
Material Code: 9999
Material Name: other -
Case No.: Not reported
Material FA: Other
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported